

No more filing or losing reports



Innovative web database

1500 pieces of equipment on line


Problem

1. Site engineers having to file off a large number of reports in short time space
2. Site engineers having to find reports at breakdowns during year
3. Insufficient information from customer given at breakdown reporting
4. Effective reporting for auditors
5. Communication with specialist companies when problems occur
6. Multiple pump failures in same location
7. Same pump failure in multiple locations
8. Accessing information by field engineers when out of office
9. Forward work planning

Solution

1. No filing for site engineers
2. Access on line service records using serial number, drive number or order number search 24/7
3. Access to pump records detailing pump type, model, serial #, port size, motor kW, photo, site map 24/7
4. Recording of use of food grade oil
5. Site engineer and specialist can communicate off the same page
6. Services stacked against pump location highlighting multiple failures, indicating potential process problem
7. Services stacked against pump serial number highlighting multiple failures, indicating pump problem
8. Data base available by remote access
9. Reports available for remedial work and next service due

mbar Ltd © 2010



mbar Ltd

EST. 2001—NATIONWIDE

**VACUUM PUMP & BLOWER
OVERHAUL SPECIALISTS**

**ANY WHERE
ANY TIME
ANY BRAND**



100% NZ

www.mbar.co.nz

24 hr phone 07 871 8192